



EARTH-CHAIN

MagVISE
Magnetic Workholding



**NEW &
EXCITING
TECHNOLOGY**

Advantages:

- *Cut setup time in half*
- *Faster part change-over*
- *Better surface finish & tool life*
- *Spring-loaded induction blocks adjust to hold warped stock*
- *Machine on 5 sides*


Choose the system that's right for your application.

EPPM Electro-Permanent Chucks



- *Magnetic chucks - 26 sizes - includes controller*
- *Electricity only needed for turning on & off*
- *Keeps holding even during a power loss*

ECB Permanent Magnetic Vises



Spring-loaded induction blocks work with both EPPM and ECB systems to hold warped stock.

- *Modular magnetic vise system - 4 sizes*
- *No electricity needed*
- *Powerful "rare earth" magnets never fail*

Magnetic workholding is faster and easier to use than traditional workholding methods, and it improves part quality while extending cutting tool life because of its superior vibration dampening characteristics. Call (877) 354-3837 or (317) 803-8034 for more info.



Cut Setup Times

Use EZ-Lift Magnets to move it, hold it with Magnetic Workholding.

Ph. (877) 354-3837

Local: (317) 803-8034
email: info@earthchain.com
www.earthchain.com